Changed Pages
Part III, Attachment III-E
Geology Report

Part III Attachment III-E

GEOLOGY REPORT

Pescadito Environmental Resource Center
MSW No. 2374
Webb County, Texas

PESCADITO ENVIRONMENTAL RESOURCE CENTER

Initial Submittal March 2015
Revised September 2015
Revised November 2015
Revised January 2016
Technically Complete March 11, 2017
Modified August 2017

Prepared for:


Rancho Viejo Waste Management, LLC 1116 Calle del Norte Laredo, TX 78041

Prepared by:

APTIM Environmental & Infrastructure, Inc. (f/k/a CB&I Environmental & Infrastructure, Inc.)



12005 Ford Rd, Suite 600 Dallas, TX 75234



This document is released for the purpose of permitting only under the authority of Michael W. Oden, P.E #67165. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650.

Table of Contents

1.0	Introduction.		1
2.0	Hydrogeolog	ic Setting	4
Figure	: III-E.0-1 — O	riginal and Revised Permit Boundaries	.12
Figure 2 – Generalized Conceptual Model of Site Hydrogeology			.10
Appen	dix III-E.1	Regional Geology and Hydrogeology	
Appen	dix III-E.2	Subsurface Investigation Report	
Appen	dix III-E.3	Geotechnical Data Report	
Appen	dix III-E.4	Summary of Hydrogeologic Testing in Selected Piezometers	
Appen	dix III-E.5	Supplemental Subsurface Investigation Report – Phase V	

i

MICHAEL W. ODEN

67165

ONAL ENGLISH

WHAT WAS

This document is released for the purpose of permitting only under the authority of Michael W. Oden, P.E #67165. It is not to be used for bidding or construction. Texas Registered Engineering Firm F-5650.

